

# CHEVROLET DOOR LOCKS

General information as follows:

1. For applications before 1967 (B10 & B11 keys) see the separate section.
2. Key blank references are for the profile only, using one of the more well-known blank numbers. This list does not include all variations of different head shapes, lengths, or transponders, the main object is to identify which key profile enters the lock.
3. Unless specified otherwise all locks using single sided keys GM-A through GM-K have universal groove that will accept all 8 keyway variations. These locks will not accept the pre-1967 B10/B11 keys.
4. Unless specified otherwise pawls are not included with replacement locks, the original pawls must be reused.
5. Items marked DWO are discontinued when out. The part numbers are listed for the benefit of those who already have stock.

**IMPORTANT:** RIGHT SIDE (RH) is the PASSENGER SIDE, LEFT SIDE (LH) is the DRIVER SIDE. If only one part number is listed, that part number can be used on either side.

Chevrolet medium and heavy duty trucks are listed in a separate section at the end of the main section. Pickups and light duty vans are listed in the main section.

Model	Years	Key	Part description	Part no.	Part description	Part no.	Notes
Astro van	1984-95	GMA/K	Uncoded service pack (front doors and side door)	D-41-203	Use face cap RP6036 (P-41-201) chrome or RP6520 (P-41-202) black Use tumbler series P-41-101/105		
			4-piece lock set (2 front door locks, side door lock, rear cargo door lock) non-electric	DL1515	same as DL1515 except with electric switch on the rear cargo door lock	DL1516 (DWO)	
Astro van	1996-05	B97	Use face cap RP6036 (P-41-201) chrome or RP6520 (P-41-202) black Replacement locks available from Strattec Use tumbler series P-41-161/164				
Avalanche	1999-00	B99	Replacement locks available from Strattec				
Avalanche	2002-06	B99	Coded lock	D-41-007	Includes extra tumblers for rekeying. without destroying it.		The face cap can be removed
Avalanche	2007-13	B111	Replacement locks available from Strattec				
Aveo hatchback	2004-11	DWO4R	Complete lock RH Includes pawl	D-50-115	Complete lock LH Includes pawl	D-50-116	Use tumbler series P-13-101/104 (P-21-111/114)
Aveo sedan	2004-06	DWO4R	Complete lock RH Includes pawl	D-50-115	Complete lock LH Includes pawl	D-50-116	Use tumbler series P-13-101/104 (P-21-111/114)
Aveo sedan	2007-11	DWO4R	Complete lock RH Includes pawl	D-50-117	Complete lock LH Includes pawl	D-50-118	Use tumbler series P-13-101/104 (P-21-111/114)
Bel Air	1967-up	GMA/K	see Caprice				
Beretta	1987-96	GMA/K	Replacement locks available from Strattec Use tumbler series P-41-101/105				
Biscayne	1967-up	GMA/K	see Caprice				
Blazer C/5, K/5 (full size)	1967-91	GMA/K	Uncoded service pack (chrome)	DL1580U	Coded pair (chrome)	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			Uncoded service pack (black)	DL1525U	Coded pair (black)	DL1525	Use face cap RP6520 (P-41-202) Use tumbler series P-41-101/105
Blazer K1500 (full size)	1992-94	GMA/K	Coded pair	DL1539	Coded 3-piece set 2 front doors + tailgate	DL1518 (DWO)	
			Uncoded service pack	DL1539U	Use tumbler series P-41-101/105		
Blazer S10 (compact size)	1982-94	GMA/K	Uncoded service pack (chrome)	DL1580U	Coded pair (chrome)	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			Uncoded service pack (black)	DL1525U	Coded pair (black)	DL1525	Use face cap RP6520 (P-41-202) Use tumbler series P-41-101/105

Scroll down for more

# CHEVROLET DOOR LOCKS

Blazer	1995-05	B97	Replacement locks available from Strattec Use tumbler series P-41-161/164				
Blazer	2019	HU100			Replacement locks available from Strattec Use tumbler series P-23-121/134		
Bolt	2017-19	HU100			Replacement locks available from Strattec Use tumbler series P-23-121/134		
Camaro	1967-12/69	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Camaro	1/70-78	GMA/K	Uncoded service pack	DL1581U	Coded pair	DL1581	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			NOTE: DL1581U / DL1581 long style door locks are officially the correct locks to use on this model range. Some cars in this range have also been found to use the short door locks (DL1580U / DL1580) or medium door locks (DL1582U / DL1582). To be sure compare the lock that was originally installed on the car, the correct length replacement must be used or the pawl will not fit and function properly.				
Camaro	1979-81	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Camaro	1982-92	GMA/K	Uncoded service pack (chrome)	DL1580U	Coded pair (chrome)	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			Uncoded service pack (black)	DL1525U	Coded pair (black)	DL1525	Use face cap RP6520 (P-41-202) Use tumbler series P-41-101/105
Camaro	1993-02	GMA/K	Uncoded service pack (black)	DL6553U (DWO)	Coded pair (black)	DL6553 (DWO)	Use face cap RP6520 (P-41-202) Use tumbler series P-41-101/105
			Uncoded service pack (chrome)	DL6943U (DWO)	Coded pair (chrome)	DL6943	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Camaro	2010-19	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				
Caprice	1967-70	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Caprice	1971-76	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Caprice (also Impala)	1977-96	GMA/K	Uncoded service pack chrome	DL1580U	Coded pair chrome	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			Uncoded service pack black	DL1525U	Coded pair black	DL1525	Use face cap RP6520 (P-41-202) Use tumbler series P-41-101/105
Caprice PPV Police vehicle	2011-13	GM45P	Replacement locks available from GM dealers only Tumblers and service parts are not available.				
Caprice PPV Police vehicle	2014-16	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				
Captiva	2011-15	B114R	Uncoded service pack LH	D-50-120	Lock service pack includes tumblers and springs for assembly. Tumblers are also available separately P-13-101/104 (P-21-111/114)		
Cavalier	1982-94	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Cavalier	1995-05	B85	Replacement locks available from Strattec Use tumbler series P-41-161/164				
Celebrity	1983-91	GMA/K	Uncoded service pack chrome	DL1580U	Coded pair chrome	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			Uncoded service pack black	DL1525U	Coded pair black	DL1525	Use face cap RP6520 (P-41-202) Use tumbler series P-41-101/105
Chevelle	1967-77	GMA/K	see Malibu				
Chevette	1975-87	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Chevy II	1967-75	GMA/K	see Nova 1967-75				
Citation	1978-84	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
City Express	2016-18	DA34	Replacement locks available from GM dealers only Use tumbler series P-16-181/184				
C/K Pickup (full size)	1967-87	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
C/K Pickup (full size)	1988-94	GMA/K	Uncoded service pack	DL1539U	Coded pair	DL1539	Use tumbler series P-41-101/105
C/K Pickup (full size)	1995-98	B97	Coded pair	DL1988	Use tumbler series P-41-161/164		
C/K Pickup (full size) GMT400 series	1999-00	B97	Coded pair	DL1988	Use tumbler series P-41-161/164		
			NOTE YEAR OVERLAPS: In 1999 these trucks were produced in both the old style GMT400 and the new style GMT800 series. For 2000 the 2500 and 3500 Crew Cab and Chassis Cab were produced as the old GMT400 series.				
C/K Pickup (full size) GMT800 series	1999-00	B99	Replacement locks available from Strattec				
C/K Pickup (full size) GMT800 series	2001-06	B99	Coded lock	D-41-007	Includes extra tumblers for rekeying. The face cap can be removed without destroying it.		

Scroll down for more

# CHEVROLET DOOR LOCKS

C/K Pickup (full size) GMT800 series Canada Silverado Classic	2007-09	B99	Coded lock	D-41-007	Includes extra tumblers for rekeying. The face cap can be removed without destroying it.		
C/K Pickup (full size) GMT900 series	2007-13	B111	NOTE: Some 2007 models used the same locks as 2006, identify by the keyway Replacement locks available from Strattec				
C/K Pickup (full size)	2014-19	HU100	NOTE: Some 2014 models used the same locks as 2013, identify by the keyway. Replacement locks available from Strattec Use tumbler series P-23-121/134				
Cobalt	2005-10	B111	Coded lock	D-41-006	Includes extra tumblers for rekeying. The face cap can be removed without destroying it.		
Colorado	2004-12	B110	Complete lock RH	D-24-122	Complete lock LH	D-24-123	Use face cap P-30-268 Use tumbler series P-24-121/124
Colorado	2015-19	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				
Corsica	1987 to 1988 mid-year	GMA/K	Uncoded service pack (chrome)	DL1580U	Coded pair (chrome)	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			Uncoded service pack (black)	DL1525U	Coded pair (black)	DL1525	Use face cap RP6520 (P-41-202) Use tumbler series P-41-101/105
			Note there was a mid-year change in 1988 from the short plug to the medium plug				
Corsica	Mid-year 1998 To 1996	GMA/K	Uncoded service pack (chrome)	DL1582U	Coded pair (chrome)	DL1582	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			Uncoded service pack (black)	DL1527U	Coded pair (black)	DL1527	Use face cap RP6520 (P-41-202) Use tumbler series P-41-101/105
Corvaire	1967-69	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Corvette	1967	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Corvette	1968	GMA/K	Push button design lock, no longer available. Try classic Corvette parts specialists. Use tumbler series P-41-101/105				
Corvette	1969-82	GMA/K	Uncoded service pack no alarm, non lighted	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			Coded pair with factory alarm	DP-41-115	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105		
Corvette	1983-90	GMA/K	Coded plugs – keyed alike pair (random keyway)	DP-41-315	Complete lock available from Strattec Use tumbler series P-41-101/105		
Corvette	1991-96	GMA/K	Uncoded plug (accepts GM-H keyway only)	D-41-302	Coded plugs – keyed alike pair (random keyway)	DP-41-315	Complete lock available from Strattec Use tumbler series P-41-101/105
Corvette	1997-04	B85	Replacement locks available from Strattec				
Corvette	2005-19		No lock cylinders, remote control release only				
Cruze	2011-19	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				
El Camino	1967-78	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
El Camino	1979-89	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Epica (Canada)	2004-06	DWO5R	Complete lock RH Includes pawl	D-50-121	Complete lock LH Includes pawl	D-50-122	Use tumbler series P-13-101/104 (P-21-111/114)
Equinox	2005-06	B99	Replacement locks available only from Chevrolet / GM dealers Use tumbler series P-41-111/114				
Equinox	2007-09	B111	Uncoded service pack	D-41-003	Use tumbler series P-41-011/015 for D-41-003 sold by ASP. Different tumblers may be used for locks not sold by ASP including some locks sold by GM dealers or originally installed on the car when it was new.		
Equinox	2010-19	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				
Eurosport	1983-91		see Celebrity				
Express van (full size)	1996-08	B99	Replacement locks available from Strattec Use tumbler series P-41-161/164				
Express van (full size)	2009-14	B111	Replacement locks available from Strattec				
Express van (full size)	2015-19	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				
G series van (full size)	1967-95	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			Lock separate from the door handle only, locks designed with the cylinder in the push button are no longer available.				
HHR	2006-11	B99	Uncoded service pack	D-41-003	Use tumbler series P-41-011/015 for D-41-003 sold by ASP. Different tumblers may be used for locks not sold by ASP including some locks sold by GM dealers or originally installed on the car when it was new.		
Impala	1967-99		see Caprice				
Impala	2000-05	B97	Coded lock	D-41-007	Includes extra tumblers for rekeying. The face cap can be removed without destroying it.		

Scroll down for more

# CHEVROLET DOOR LOCKS

Impala LT, Police	2006-16	B111	Replacement locks available from Strattec				
Impala	2014-19	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				
Lumina 2-door	1989-94	GMA/K	Uncoded service pack	DL1508U (DWO)	Coded pair	DL1508	Use tumbler series P-41-101/105
Lumina 4-door	1989-01	GMA/K	Uncoded service pack (chrome)	DL1580U	Coded pair (chrome)	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			Uncoded service pack (black)	DL1525U	Coded pair (black)	DL1525	Use face cap RP6520 (P-41-202) Use tumbler series P-41-101/105
Lumina van APV	1990-96	GMA/K	Uncoded service pack without factory alarm or automatic locking (1990-96)	D-41-203	Use chrome face cap RP6036 (P-41-201) Use black face cap RP6045 (P-41-202) Use tumbler series P-41-101/105		
			Uncoded service pack with factory alarm or automatic locking (1991-96 only)	D-41-216	NOTE: D-41-216 uses H keyway used on 1991-96 models only. Uncoded service package not available with other keyways as used 1990 Use chrome face cap RP6036 (P-41-201) Use black face cap RP6045 (P-41-202) Use tumbler series P-41-101/105		
LUV	1972-80	P1098V	Complete lock with reversible pawl R&L	D-24-102 (DWO)	Available only with X54 / DC1 keyway. Use face cap P-24-201 (DWO) Use tumbler series P-30-141/144		
LUV	1981-87	DC1	Uncoded service pack	D-24-201	Use pawl P-30-322 (right side) or P-30-323 (left side) Use face cap P-24-203 (chrome) or P-24-204 (black) Use tumbler series P-30-141/144		
Malibu	1967-78	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Malibu 2-door	1979-84	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Malibu 4-door & wagon	1979-84	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Malibu	1997-03	B97	Coded lock	D-41-007	Includes extra tumblers for rekeying. The face cap can be removed without destroying it.		
Malibu (except Malibu Classic)	2004-12	B111	Uncoded service pack	D-41-003	Use tumbler series P-41-011/015 for D-41-003 sold by ASP. Different tumblers may be used for locks not sold by ASP including some locks sold by GM dealers or originally installed on the car when it was new.		
Malibu Classic	2004-06	B97	Coded lock	D-41-007	Includes extra tumblers for rekeying. The face cap can be removed without destroying it.		
Malibu Maxx	2004-07	B111	Uncoded service pack	D-41-003	Use tumbler series P-41-011/015 for D-41-003 sold by ASP. Different tumblers may be used for locks not sold by ASP including some locks sold by GM dealers or originally installed on the car when it was new.		
Malibu	2013-19	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				
Metro	1995-97	B65	Coded lock (no pawl)	D-33-207	Previously sold as D-33-107 (RH) and D-33-108 (LH) If the original pawl cannot be reused, use P-33-303 (RH) or P-33-304 (LH) Use face cap P-30-217 Use tumbler series P-30-161/164		
Metro	1998-01	B69	Uncoded service pack	D-33-204	Original pawls must be reused. Use face cap P-20-265 Use tumbler series P-33-101/105		
Monte Carlo	1970-78	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Monte Carlo	1979-89	GMA/K	Uncoded service pack (chrome)	DL1582U	Coded pair (chrome)	DL1582	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			Uncoded service pack (black)	DL1527U	Coded pair (black)	DL1527	Use face cap RP6520 (P-41-202) Use tumbler series P-41-101/105
Monte Carlo	1995-99	B99	Replacement locks available from Strattec Use tumbler series P-41-161/164				
Monte Carlo	2000-05	B97	Coded lock	D-41-007	Includes extra tumblers for rekeying. The face cap can be removed without destroying it.		
Monte Carlo	2006-08	B111	Uncoded service pack	D-41-003	Use tumbler series P-41-011/015 for D-41-003 sold by ASP. Different tumblers may be used for locks not sold by ASP including some locks sold by GM dealers or originally installed on the car when it was new.		
Monza	1975-80	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Nova	1967-75	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Nova	1984-88	TR33	Lock service package	D-30-206	Coded pair includes pawls	DP-30-106	If original pawl cannot be reused, use P-30-312 (RH) or P-30-313 (LH) Use face cap P-30-271 Use tumbler series P-30-141/144
Optra (Canada)	2004-06	DWO4R	Complete lock RH	D-50-123	Complete lock LH	D-50-124	Use tumbler series P-13-101/104 (P-21-111/114)
Orlando	2012-14	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				

Scroll down for more

# CHEVROLET DOOR LOCKS

Pickup	All		See the individual models: Full size pickup - see C/K series Compact size pickup - see LUV, S10, Colorado Specialty pickup – see El Camino, SSR, Avalanche				
Prizm	1998-02	TR47 8-cut	Complete lock RH Includes pawl	D-30-171	Complete lock LH Includes pawl	D-30-172	Use face cap P-30-265 Use tumbler series P-30-181/188
S10 Pickup	1982-94	GMA/K	Uncoded service pack (chrome)	DL1580U	Coded pair (chrome)	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			Uncoded service pack (black)	DL1525U	Coded pair (black)	DL1525	Use face cap RP6520 (P-41-202) Use tumbler series P-41-101/105
S10 Pickup	1995-04	B97	Replacement locks available from Strattec Use tumbler series P-41-161/164				
Silverado	All		See C/K Pickup (full size pickup)				
Spectrum	1985-91	B53	Uncoded service pack without pawl	D-24-202	Uncoded plug	D-24-302	Use face cap P-30-271 (chrome) or P-30-215 (black) Use tumbler series P-24-101/104
Sprint (Swift)	1985-88	DC1	Complete lock with reversible pawl	D-33-101	Coded pair with pawls	DP-33-101	Use face cap P-24-203 (old part no. P-30-202). Use tumbler series P-30-141/144
Sprint (Swift)	1989-94	B65 (X185)	Uncoded service pack	D-33-205	Previously sold as D-33-105 (RH) and D-33-106 (LH) If original pawl cannot be reused, use P-33-301 (RH) or P-33-302 (LH) Use tumbler series P-30-161/164		
Sonic	2012-18	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				
Spark	2013-15	DWO4C	Uncoded service pack RH	D-50-125	Uncoded service pack LH	D-50-126	Lock service pack includes tumblers and springs for assembly. Tumblers are also available separately P-13-101/104 (P-21- 111/114)
Spark EV	2016	DWO4C	Uncoded service pack RH	D-50-125	Uncoded service pack LH	D-50-126	Lock service pack includes tumblers and springs for assembly. Tumblers are also available separately P-13-101/104 (P-21- 111/114)
Spark Except EV	2016-18	HU100	Replacement locks available from GM dealers only Use tumbler series P-23-121/134				
SS	2014-16	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				
SSR	All	B99	Replacement locks available from Chevrolet / GM dealers only. Face cap must be removed to service original lock on the car, replacement caps not currently available Use tumbler series P-41-111/114				
Suburban	1967-91	GMA/K	Uncoded service pack (chrome)	DL1580U	Coded pair (chrome)	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			Uncoded service pack (black)	DL1525U	Coded pair (black)	DL1525	Use face cap RP6520 (P-41-202) Use tumbler series P-41-101/105
			3-piece lock set (2 front doors + rear door) – chrome only	DL1517	NOTE: DL1517 is used only for Suburban with swing out rear doors. Lock set is not available for Suburban with drop down rear tailgate.		
Suburban	1992-94	GMA/K	Coded pair	DL1539	Coded 3-piece set 2 front doors + tailgate	DL1518 (DWO)	
			Uncoded service pack	DL1539U	Use tumbler series P-41-101/105		
Suburban	1995-99	B97	Coded pair	DL1988	Use tumbler series P-41-161/164		
Suburban	2000	B99	Replacement locks available from Strattec				
Suburban	2001-06	B99	Coded lock	D-41-007	Includes extra tumblers for rekeying. The face cap can be removed without destroying it.		
Suburban	2007-14	B111	Replacement locks available from Strattec				
Suburban	2015-19	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				
Tahoe	1995-00	B97	Coded pair	DL1988	Use tumbler series P-41-161/164		
Tahoe	2001-06	B97	Coded lock	D-41-007	Includes extra tumblers for rekeying. The face cap can be removed without destroying it.		
Tahoe	2007-14	B111	Replacement locks available from Strattec				
Tahoe	2015-19	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				
Tracker	1999-04	B69	Uncoded service pack	D-33-204	Original pawls must be reused. Use face cap P-20-265 Use tumbler series P-20-131/155		
Trailblazer	2002-09	B97	Coded lock	D-41-007	Includes extra tumblers for rekeying. The face cap can be removed without destroying it.		
Traverse	2009-17	B111	Uncoded service pack	D-41-003	Use tumbler series P-41-011/015 for D-41-003 sold by ASP. Different tumblers may be used for locks not sold by ASP including some locks sold by GM dealers or originally installed on the car when it was new.		
Traverse	2018-19	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				

Scroll down for more

# CHEVROLET DOOR LOCKS

Trax	2015-19	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				
Uplander	2005-07	B107	Locks using B107 keys, available from Chevrolet / GM dealers only. Use tumbler series P-41-011/015				
		B86	Locks using B86 keys, available from Strattec Use tumbler series P-41-161/164				
Van	All		See the individual models: Full size van – see G-series or Express Compact size van – see Astro Minivan – see Lumina, Venture, Uplander Specialty van – see HHR				
Vega	1971-77	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Venture	1997-05	B97	Replacement locks available from Strattec				
Volt	2011-19	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				

# CHEVROLET MEDIUM AND HEAVY DUTY TRUCKS

C40-C70 (Medium Duty)	1967-90	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
C40-C70 (Medium Duty)	1991-94	GMA/K	Uncoded service pack	DL1539U	Coded pair	DL1539	Use tumbler series P-41-101/105
Kodiak (Medium Duty)	1995-02	GMA/K	Uncoded service pack	DL1539U	Coded pair	DL1539	Use tumbler series P-41-101/105
Kodiak (Medium Duty)	2003-05	B97	Replacement locks available from Strattec Use tumbler series P-41-161/164				
LCF 3500, 4500, 5500	2008-18	X275	Replacement locks available from Chevrolet / GM dealers only. Tumblers and other service parts are not available.				
Titan 90 heavy duty truck	1980-87	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
W4, W5 Tiltmaster	1986-87	B57	Coded lock without pawl	D-24-107 (DWO)	If original pawl cannot be reused, use P-30-324 (RH) or P-30-325 (LH) Use face cap P-30-271 Use tumbler series P-24-101/104		
W4, W5 Tiltmaster	1988-07	B65	Complete lock LH (including LH pawl)	D-24-118	Right side door lock previously available as D-24-117. Now use D-24-118 and reuse the original right side pawl. Use face cap P-30-271 Use tumbler series P-30-161/164		
W6, W7 Forward	All using B54 key	B54	Coded pair (must reuse original pawls)	DP-16-106	NOTE: DP-16-106 is available with DA25 keyway only and cannot be rekeyed to the original B54 key. Locks using the B54 keyway previously available as D-24-108, now available from Chevrolet / GMC / Isuzu truck dealers only. Use face cap P-16-205 (for original locks and DP-16-106) Use tumbler series P-16-161/164 (for original locks and DP-16-106)		

Scroll down for tumbler and keying kit information

# CHEVROLET DOOR LOCKS

## Which tumblers and keying kits to use:

The chart below lists which tumblers and keying kits to use according to which key blank the lock uses.

General Motors is different from most other car manufacturers because locks using the same keyway may use different tumblers depending upon who manufactured the lock and in some cases when it was manufactured. Also some replacement locks may use tumblers different from the lock installed on the car when it was built and which are not available from any known source. As such these tumbler references are correct only to the extent of information that is available to us.

To help avoid confusion, whenever possible the year and model section includes which tumbler series to use in the notes section.

Key Blank	Tumbler #1 depth	Tumbler #2 depth	Tumbler #3 depth	Tumbler #4 depth	Tumbler #5 depth	Keying kits and Notes
B10, B11	P-41-101 RP6038 322051	P-41-102 RP6039 322052	P-41-103 RP6040 322053	P-41-104 RP6041 322054	P-41-105 RP6042 322055	SK6035 keying kit supplied by ASP
B53, B57	P-24-101	P-24-102 (DWO)	P-24-103	P-24-104 (DWO)		Contained in A-24-101 and A-30-150 keying kits which are no longer available for purchase. Refill packs of the individual tumblers will continue to be available until sold out.
B54	P-16-161	P-16-162	P-16-163	P-16-164		A-16-106 current keying kit  Also contained in the A-16-100 and A-16-101 keying kits which are no longer available for purchase.
B65	P-30-161	P-30-162	P-30-163	P-30-164		A-30-106 current keying kit  Also contained in the A-30-150 keying kit which is no longer available for purchase.
B69	P-20-131	P-20-132	P-20-133	P-20-144	P-20-155	A-20-103 current keying kit containing only this series  A-20-150 current keying kit containing this and the MZ13 series  Also contained in keying kit A-20-100 and A-20-102 no longer available for purchase (DWO)
B85, B89, B97, B99 Locks made by Lockcraft and Strattec	P-41-161 RP6420 322241	P-41-162 RP6421 322242	P-41-163 RP6422 322243	P-41-164 RP6423 322244		A-41-102 keying kit assembled by ASP (DWO) SK6400 keying kit assembled by Lockcraft (DWO) Refill parts will be available until sold out, tumblers made by Strattec will also work in these locks.
B85, B89, B97, B99 Locks made by Ortech sold by ASP	P-41-121	P-41-122	P-41-123	P-41-124		A-41-104 current keying kit  Also contained in keying kit A-41-150 which is no longer available for purchase
B85, B89, B97, B99 Locks made by HUF	P-41-111	P-41-112	P-41-113	P-41-114		A-41-103 current keying kit  Also contained in keying kit A-41-150 which is no longer available for purchase
B102, B107, B111 Locks made by Ortech sold by ASP	P-41-011	P-41-012	P-41-013	P-41-014	P-41-015	Contained in keying kit A-41-152 which is no longer available for purchase.  Refill packs of the individual tumblers will continue to be available until sold out.
B102, B107, B111 Locks made by Strattec						These tumblers are only available from Strattec, several different designs are used, check according to the exact year and model application that you are working on.
B110	P-24-121	P-24-122	P-24-123	P-24-124		A-24-103 current keying kit

Scroll down for more

# CHEVROLET DOOR LOCKS

B114R (except ignition locks)	P-13-101 Or P-21-111	P-13-102 Or P-21-112	P-13-103 Or P-21-113	P-13-104 Or P-21-114		A-13-101 current keying kit for this series only  Also contained in the A-21-101 keying kit  Also contained in the A-41-152 keying kit which is no longer available for purchase.  Refill packs may be ordered under the P-13-101/104 or P-21-111/114 part numbers, same parts at the same price.
DA34	P-16-181	P-16-182	P-16-183	P-16-184		A-16-108 current keying kit  Also contained in the A-16-101 keying kit which is no longer available for purchase.
DC1, DC3 (P1098V)	P-30-141	P-30-142	P-30-143	P-30-144		A-30-116 current keying kit  Also contained in the A-30-104 and A-30-150 keying kits which are no longer available for purchase.
DWO4R DWO4C (DWO4CT6)	P-13-101 Or P-21-111	P-13-102 Or P-21-112	P-13-103 Or P-21-113	P-13-104 Or P-21-114		A-13-101 current keying kit for this series only Also contained in the A-21-101 keying kit  Also contained in the A-41-152 keying kit which is no longer available for purchase.  Refill packs may be ordered under the P-13-101/104 or P-21-111/114 part numbers, same parts at the same price.
GMA through GMK (single sided keys, sidebar locks)	P-41-101 RP6038 322051	P-41-102 RP6039 322052	P-41-103 RP6040 322053	P-41-104 RP6041 322054	P-41-105 RP6042 322055	SK6035 keying kit supplied by ASP
HU100	P-23-121 (1R)	P-23-122 (2R)	P-23-123 (3R)	P-23-124 (4R)		A-23-103 current keying kit
	P-23-131 (1L)	P-23-132 (2L)	P-23-133 (3L)	P-23-134 (4L)		
TR33	P-30-141	P-30-142	P-30-143	P-30-144		A-30-116 current keying kit  Also contained in the A-30-104 and A-30-150 keying kits which are no longer available for purchase.
TR47 8-cut	#1 depth full size P-30-181	#2 depth full size P-30-182	#3 depth full size P-30-183	#4 depth full size P-30-184		A-30-108 current keying kit  Also contained in the A-30-114 and A-30-150 keying kits which are no longer available for purchase.
	#1 depth split P-30-185	#2 depth split P-30-186	#3 depth split P-30-187	#4 depth split P-30-188		NOTE in this series #1 is the deepest cut, #4 is full width of the key blade
	#1 depth special design P-30-701	#2 depth special design P-30-702	#3 depth special design P-30-703	#4 depth special design P-30-704		These are special extra wide wafers which can replace the side-by-side split wafers. A-30-117 keying kit

## Tumbler springs:

For sidebar locks using single bitted keys B10, B11, GMA/GMK - part no. RP6037 (P-41-100)

For locks using double bitted keys B97, etc. - part no. RP6419

For locks using DWO4R, DWO4C keys - part no. P-31-100

For locks using HU100 2-track high security keys - part no. P-31-100

For locks using TR47, B110, DA34, DC1, TR33, and other similar keys (Japanese design locks)

P-00-100 - currently active part number - 100 springs per pack

This spring can also be substituted to use in locks using double bitted keys B97, etc.:

Part numbers previously used, now superseded to P-00-100

P-16-105	P-30-108
P-19-100	RP6546
P-20-105	RP6612
P-20-115	RP6731
P-24-105	RP6822
P-30-105	